Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	199	702/85.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:27
S2	2	"6091281".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:31
S3	2	"5764048".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:39
S4	6	455/130.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:40
S5	1	455/63.3.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:41
S6	7	455/67.13.ccls. and calibrating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:59
S7	0	remote near calibrating near measuring near instrument	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 13:59
S8	1883	remote and calibrating and measuring and instrument	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:00
\$9	621	(remote and calibrating and measuring and instrument) and converting	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ΘN	2004/11/05 14:08

S10	478	((remote and calibrating and measuring and instrument) and converting) and standard	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:08
S11	474	(((remote and calibrating and measuring and instrument) and converting) and standard) and reference	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:08
S12	1244	(remote and calibrating and measuring and instrument) and frequency	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:09
S13	366	((remote and calibrating and measuring and instrument) and converting) and (((remote and calibrating and measuring and instrument) and converting) and standard) and ((((remote and calibrating and measuring and instrument) and converting) and standard) and reference) and ((remote and calibrating and measuring and instrument) and frequency)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/05 14:09